



LIST OF CONTENTS

SUSAN BARR	Introduction	9
SUSAN BARR	Management of IPY stations in the Norwegian Arctic	11
CORNELIA LÜDECKE	German Meteorological Stations in northwest Svalbard	18
JOHAN MATTSSON AND ANNE-CATHRINE FLYEN	Bio-deterioration in buildings in Svalbard	23
ROBERT A. BLANCHETTE	Northumberland House, Fort Conger and the Peary Huts in the Canadian High Arctic: current conditions and assessment of wood deterioration taking place	30
RICARDO ROURA	Antarctic Research stations: Environmental and cultural heritage perspectives 1983-2008	38
MICHAEL MORRISON	Observations on standards of management and maintenance	51
ROBERTA FARRELL AND SHONA DUNCAN	Scientific Evaluation of Deterioration of Historic Huts of Ross Island, Antarctica	59
JOHN GREENWOOD AND MEGAN ABSOLON	Challenges of Conservation in the Antarctic	65
ADAM WILD	minus six degrees of separation (Ross Sea restoration project)	71
BRETT E. ARENZ AND ROBERT A. BLANCHETTE	East Base, SOS: Assessment of deterioration and recommendations for conserving this important Antarctic historic site	78
RUBEN STEHBERG MICHAEL PEARSON ANDRÉS ZARANKÍN XIMENA SENATORE CAROLINA GATICA	Protection and preservation of the oldest sites of the Antarctic: the case of Fildes Peninsula and Byers Peninsula in the South Shetland Islands	85
PAUL CHAPLIN	Pole to Pole: video-telephone discussion between Scott Base, Antarctica and the IPHC conference in Barrow, Alaska	94